MATERIAL SAFETY DATA SHEET

REMINGTON ARMS COMPANY, INC.
870 REMINGTON DRIVE
MADISON, NC 27025-0700

DATE: April 19, 2010

DOT HAZARD CLASS: N/A.

DOT SHIPPING NAME: N/A.

TELEPHONE NUMBERS:
Product Info - 336/548-8700 or 800/243-9700
Emergency - CHEMTREC 800/424-9300

SECTION I - PRODUCT IDENTIFICATION

FORMULA NUMBER: MFG. #10BQ16A16
PRODUCT NUMBER: #19952
PRODUCT NAME: **Rem® Dri 35 Desiccant Dehumidifier Packet**
PRODUCT CLASS: Carbon/Silica Gel Blend

SECTION II - HAZARDOUS INGREDIENTS

INGREDIENT	CAS#	% WT.	OCCUPATIONAL EXPOSURE LIMITS TLV	PEL	VAPOR MM	@ º C
SILICA GEL	62331-67-4	<80	NE	NE	NE	NE
CARBON	7440-440	<30	NE	NE	NE	NA

* Indicates toxic chemical(s) subject to the reporting requirements of 29 CFR 1910.1200 (see Section 3 for Hazardous Identification and Section 8 for Exposure Guidelines).

SECTION III - PHYSICAL DATA

BOILING POINT: N/A
FREEZING POINT: N/A
SOLUBILITY IN WATER: Negligible.

APPEARANCE: White & black granules
BULK DENSITY: Approx. 0.75 g/cc

SECTION IV - FIRE FIGHTING MEASURES AND EXPLOSION HAZARD DATA

FLASH POINT: N/A

IGNITION TEMPERATURE: >400° C.

UNUSUAL FIRE AND EXPLOSION HAZARDS: When burned, hazardous products of combustion including oxides of carbon can occur. Irritating and/or toxic gases due to decomposition of the product may be generated during a fire. Contact with strong oxidizers such as ozone or liquid oxygen may cause rapid combustion.

EXTINGUISHING MEDIA: Use dry chemical, water fog, foam, or carbon dioxide.

SPECIAL FIREFIGHTING PROCEDURES: Wear full protective clothing and NIOSH approved self-contained breathing apparatus.

SECTION V - HEALTH HAZARD & FIRST AID MEASURES

NEVER ENTER A CONFINED SPACE CONTAINING ACTIVATED CARBON SINCE IT CAN ABSORB OXYGEN AND ASPHYXIATION MAY RESULT.

PRIMARY ROUTES OF ENTRY: Inhalation X Ingestion X Dermal X

The primary concerns for occupational exposure are skin and inhalation in the form of dust. The dust may cause eye irritation, and possibly respiratory tract irritation that can cause coughing or sneezing. Wear protective mask if dust is present.

EMERGENCY AND FIRST AID PROCEDURES:

INHALATION -	Remove from exposed area to fresh air. Seek medical attention if any symptoms persist.
INGESTION -	Rinse mouth with water. Induce vomiting as directed by medical personnel.
SKIN CONTACT -	First aid is normally not needed. As a precaution, brush powdered material from the skin and wash with soap and water. Wash clothing.
EYE CONTACT -	Remove contact lenses. Flush with large quantities of cool water with eyelids open for at least 10 minutes. If irritation from contact persists, get medical attention.

SECTION VI - REACTIVITY DATA

STABILITY: Stable
CONDITIONS TO AVOID: N/A
INCOMPATIBILITY: Strong oxidizers such as ozone, liquid oxygen and chlorine.
HAZARDOUS DECOMPOSITION PRODUCTS: Oxides of carbon (CO and CO_2).

SECTION VII - SPILL AND LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Notify safety personnel of leaks or spills. Clean-up personnel need protection against inhalation of dust and fumes. Eye protection is required. Vacuuming and/or wet methods of clean up are preferred. Place in appropriate containers for disposal, keeping airborne particulates at a minimum.

WASTE DISPOSAL: Dispose in accordance with applicable local, state, and federal regulations.

SECTION VIII – HANDLING AND STORAGE

HANDLING: Avoid contact with eyes and skin. Avoid scattering of dust into air and breathing of dust. Keep containers dry and closed. Wash skin thoroughly after handling.

STORAGE: Product shall be stored in sealed containers in dry, well-ventilated area away from strong oxidizers (chlorine, permanganate and ozone, etc), ignition sources, combustible materials, and heat.

SECTION IX – EXPOSURE CONTROLS / PERSONAL PROTECTION

RESPIRATORY PROTECTION: Use a NIOSH approved respirator in the absence if proper environmental control.

SKIN PROTECTION: Avoid skin contact. Wear appropriate dust resistant clothing. Wash clothes and related equipment before reuse. Completely wash skin after handling. Wear gloves and long sleeve shirts to prevent long-term exposure.

EYE PROTECTION: Safety glasses with side panels are required for any form of handling.

AIRBORNE EXPOSURE GUIDELINES: OSHA and ACGIH have established an exposure limit for this material at 10 mg/m^3 Total dust.

OTHER PROTECTIVE EQUIPMENT: Usually none required.

SECTION X - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE: Do not store near flames or at elevated temperatures.

OTHER PRECAUTIONS: Read carefully all cautions and directions on product label before use. Dispose of product according to local regulations.

NOTE: THE INFORMATION CONTAINED HEREIN IS FURNISHED WITHOUT WARRANTY OF ANY KIND. EMPLOYERS SHOULD USE THIS INFORMATION ONLY AS A SUPPLEMENT TO OTHER INFORMATION GATHERED BY THEM AND MUST MAKE INDEPENDENT DETERMINATION OF SUITABILITY AND COMPLETENESS OF INFORMATION FROM ALL SOURCES TO ASSURE PROPER USE OF THESE MATERIALS AND THE SAFETY AND HEALTH OF EMPLOYEES. ANY USE OF THIS INFORMATION MUST BE DETERMINED BY THE USER TO BE IN ACCORDANCE WITH APPLICABLE FEDERAL, STATE, AND LOCAL LAWS AND REGULATIONS.